# HUBER+SUHNER® DATA SHEET Between Series Adapter: 32 MMCX-SMA-50-1/111 O

Rev.: C



## Description

Adaptor plug/plug MMCX plug (male) / SMA plug (male)

Interface standards SUHNER-MMCX



#### **Technical Data**

### **Electrical Data**

 $\begin{array}{ll} \text{Impedance} & \quad \text{50 } \Omega \\ \text{Interface frequency max.} & \quad \text{6 GHz} \\ \end{array}$ 

Frequency range DC to 2.5 GHz 2.5 to 6 GHz Return loss  $\geq$  26 dB  $\geq$  21 dB

**Mechanical Data** 

Number of matings 500 Weight 0.0058 kg

**Environmental Data** 

Operating Temperature -55 °C to 155 °C 2002/95/EC (RoHS) compliant

**Material Data** 

Piece Parts (MMCX) Material

Centre contact Copper Beryllium Alloy
Outer contact Brass
Body Brass
Insulator PFA / PTFE

Insulator PFA / PTF
Piece Parts (SMA) Material

Centre contact Copper Beryllium Alloy
Outer contact Copper Beryllium Alloy

Body Brass
Insulator PFA / PTFE
Coupling nut Bronze

Gasket MVQ (Silicone Rubber)

**Related Documents** 

**Ordering Information** 

Single package 32 MMCX-SMA-50-1/111 OE

**Surface Plating** 

Gold Plating (without Nickel underplating) Gold Plating (without Nickel underplating) Gold Plating (without Nickel underplating)

## **Surface Plating**

Gold Plating (without Nickel underplating) Gold Plating (without Nickel underplating) Gold Plating (without Nickel underplating)

Gold Plating (without Nickel underplating)

HUBER+SUHNER is certified according to ISO 9001 and ISO 14001

WAIVER!

It is exclusively in written agreements that we provide our customers with warrants and representations as to the technical contained specifications and/or the fitness for any particular purpose. The facts and figures herein are carefully compiled to the best of our knowledge, but they are intended for general informational purposes only.

**HUBER+SUHNER – Excellence in Connectivity Solutions** 

HUBER+SUHNER
HUBER+SUHNER AG

RF Technology 9100 Herisau, Switzerland Phone +41 (0)71 353 41 11 Fax +41 (0)71 353 45 90 www.hubersuhner.com

Document: DOC-0000195501 L Issued: 20.12.07 Uncontrolled Copy Page 1/1